403-521 Market Street (Houses and Commercial Buildings)
(Mill Hill Historic District)
Victor Caulkins House
403 Market Street
Trenton
Mercer County
New Jersey

HABS No. NJ-901-A

11-TRET, 12-A-

## **PHDTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, DC 20013-7127 Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## HABS NJ. 12-A-

## ARCHITECTURAL DATA FORM

			<del></del>		
	STATE	COUNTY	TOWN OR VI	CINITY	
1	New Jersey	Mercer	Tren	Trenton	
	HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.	
	Victor Caulkins House (Deed	2/4/1876)		NJ-901-A	
	CONDARY OR COMMON NAMES OF STRUCTURE				
-	Mill Hill Historic District				
	OMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 403 Market Street				
	DATE OF CONSTRUCTION (INCLUDE SOURCE) Between 1860-1874  ARCHITECT(S) (INCLUDE SOURCE)				
	Market Street Report, August, 1979				
	SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
	The Victor Caulkins House contributes to the Mill Hill Historic District, a homogeneous				
	group of residential structures representative of vernacular interpretations of popular styles built during the second half of the nineteenth century.				
	STYLE (IF APPROPRIATE) Vernacular with Italianate features				
	MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
	Brick and masonry				
ļ	SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
٠. ا	Rectangular, 22' x 69'				
	EXTERIOR FEATURES OF NOTE  3-bay, 3-story structure with raised basement; flat roof; bracketed cornice; coursed ash-				
	lar basement face; quarry-faced tooled stone water table; first floor windows have stone				
	sills and lintels INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
	Side-hall plan; vestibule has double door with sunken panels and arched openings				
	MA IOD ALTERATIONS AND ADDITIONSWITH DATES				
	MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
	Two-story rear addition built prior to 1874.				
	PRESENT CONDITION AND USE				
	Poor condition due to neglect and vandalism - unoccupied.				
	OTHER INFORMATION AS APPROPRIATE				
Ì					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Historic/Architectural Resources - Technical Support Document				-	
	Market Street Project, prepared by Heritage Studies, August, 1979.				
	COMPILER, AFFILIATION			DATE	
	•	ysis, New Jersey Dept. of Trans	sportation	8/10/81	
1	-: · =	, F		• •	